

SURVEY NOTES

11-2-76

01412 11232 32201

16112 150

25.2

2 1+2

2-1-1976

6-1-1976

CORNER RECORD (Continued)

SW CORNER SECTION 8 T14.55E MD N

Nov 6-1976

Physical Description of Found Stumps:

End. 50"x35" Stump - pretty well decayed and leaning to breaking up with large pieces lying around the base. When found on the ground, a piece with a Forest Service Corner Location Marker was found, also with chop marks that appear to have been a chisel. When broken together the Loc. Marker found the found 1 1/4" piece.

End. 28"x25" Stump - This stump is in better condition & one piece w/ Forest Service Corner Location Marker, marked "E. to Sec. Cor." on the left side & the initials of "F.V.A." and the date of "6-17-48" on the right side. There is also appears to have been a chisel & a small hole in the stump at the location of "Foot 1 1/2" I.P."

III III When referring to the original Field Notes by S.D. Bond & dated Jan. 1932

The bearing & distance of S 52 1/2° E 165 lks. (108°) was laid out as this was the most authentic of the found stumps. Then the compass was moved to the stump determined location, and the bearings checked to the other found stump. This is as the 30' line of F.S.C. (N 19° W) The Bore. Fit this location

near the distances were measured - The distance to the 26" tree of 170 lks. (116°) fit within reason, but the Record distance of 194 lks. (108°) fell 72' further west of the previously established Loc.

— It appears that in 1932 when the new tree was marked the distances were not checked. —

From on are Scribbled, by using the record distance and the two found stumps, the bearing of N 47 1/2° W 107 1/2 (703') was laid out & fell in a slight depression, which has an old stump lying 9' to 10' south of it & appears evidence of a large. The area was dug and old stumps found. The found before the 1 foot level indicating that this was the location of an old tree of one time. The distance measured 15' short of the Scribbled are using the two stumps.

The distance from the found depression & stump to the South were measured & the distance to the stump to the East was held. The new corner set at this point with all relations, shape shown in sketch on sheet 162

It appears that the bearing of S 52 1/2° E is in error and should have been S 57 1/2° E.

W. C. H. H. H.